	CONTROL BLOCK
01	C A R S 1 1 1 0 0 0 0 0 0 0
OIT	SOURCE LL 10 0 5 0 0 0 0 1 3 1 1 2 10 1 1 1 0 19 1 7 1 9 10 1 1 2 10 1 4 1 7 19 10
0 2	On 11-9-79 during routine operation the "A" Diesel Generator failed to
0 3	Latart from the control room. 'fter a second unsuccessful attempt, the
0 4	Lredundant diesel generator was started and operators dispatched to locally
0 5	Lstart the unit. Upon taking local control, the unit was started twice
0 6	Llocally and once from the control room. Since then the unit has been
0 7	successfully started 8 times without problems.
[8]	<u></u>
0 9	SYSTEM CAUSE SUBCODE S
	CAUSE DESCRIPTION AND CORPECTIVE ACTIONS (27) LER NO EVENT YEAR REPORT NO. OCCURRENCE CODE TYPE ACTION FUTURE CODE TYPE 131 ACTION FUTURE COMP SUPPLIES ATTACHMENT SUPPLIES ATTACHMENT SUPPLIES ATTACHMENT SUPPLIES ATTACHMENT SUPPLIES ATTACHMENT SUPPLIES ATTACHMENT SUPPLIES CAUSE DESCRIPTION AND CORPECTIVE ACTIONS (27) CAUSE DESCRIPTION AND CORPECTIVE ACTIONS (27)
	The cause of the start failures is unknown since the major factors
	affecting starting capability appeared normal. To assure confidence in
1 2	the unit's starting ability, it was started daily for the next 4 days.
1 3	The unit has been started on 4 separate occasions since that time. No
114	recurrence of the start problem was encountered.
15	E 3 10 0 8 N/A B ROutine Testing
1 6	TIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A N/A N/A
•	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
17	O O O O O O O O O O O O O O O O O O O
1	O O O O O O O O O O O O O O O O O O O
na i	SSS OF ON DAVIACE TO FACILITY 1 1582 029 N/A
	PUBLICITY SUFF DESCRIPTION (S) NAC USE ONLY
270	N/A I IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	NAME OF PREPARER R. W. Colombo PHONE (916) 452-3211