

MATERIAL TRANSMITTED MERSWITH

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

JAN 24 1980

Report Nos: 50-250/79-37 and 50-251/79-37

Docket Nos: 50-250 and 50-251

License Nos. DPR 31 and DPR 41

Licensee: Florida Power & Light

P. O. Box 529100 Miami, Florida 33152

Facility Name: Turkey Point, Units 3 and 4

Inspection at: Turkey Point Site near Homestead, Florida

Inspection conducted: December 11-14, 1979

Date of Last Physical Security Inspection Visit: June 11-14, 1979

Type of Inspection: Unannounced Physical Security

Inspectors: ('. N. Kluing C. D. Perny, Security Inspector

Approved by: William Tobu.
W. J. Tobin, Acting Chief, Security Section, 1-32.80

Inspection Summary

Areas Inspected: Included review of the licensee's response to IE Bulletin 79-16; Security Plan; Security Organization; Physical Barriers (Protected Area); Physical Barriers (Vital Area); Access Control (Vital Area); Detection Aids; and Compensatory Measures.

The inspection involved 26 inspector hours on site by 1 NRC inspector. The inspection was begun during an offshift period; 5 inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the 8 areas examined during the inspection.

> This Document is not to be reproduced with and specific pronounl of IT II