

TIC



LOUISIANA POWER & LIGHT / 142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

November 30, 1979

D. L. ASWELL
Vice President-Power Production

LPL 12565
Q-3-A35.07.11

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

DEC 5 1979

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Construction Deficiency Report No. 11
Switchgear Breaker Position Switch
Operator Defect

Dear Mr. Seyfrit:

As discussed with your Mr. Stewart, the planned modifications of the GE switchgear breaker position switch operators will be delayed due to a slippage in the schedule requirements of the GE technical representative. We have received the operators on site and expect replacement installation to commence in December. We now expect to be able to complete all work and submit the final report by March 31, 1979.

Yours very truly,

D. L. Aswell

DIA/TFG/grf

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

5 8002190 236