

SACRAMENTO MUNICIPAL UTILITY DISTRICT 

6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

February 25, 1980

Mr. R. H. Engelken, Director Region V Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission 1990 North California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, California 94396

Re: Operating License DPR-54
Docket No. 50-312
Reportable Occurrence 80-11

Dear Mr. Engelken:

On February 19, 1980, the Sacramento Municipal Utility District reported to your office degradation of OTSG tubes discovered during the recent inspection at Rancho Seco. The immediate notification was predicated upon Regulatory Guide 1.16, Section C.2.a(3). However, upon a closer review and referring to Regulatory Guide 1.83, Inservice Inspection of Pressurized Water Reactor Steam Generator Tubes, it was determined that the occurrence does not fall into the "immediate notification, 14-day follow-up report" category.

As a result, the occurrence will be reported under the requirements of Regulatory Guide 1.16, Section C.2.b(4) and Technical Specifications, Section 6.9.4.2(d), which specify 30-day written reports. The additional reports required by Technical Specifications, Section 4.17.5, will also besubmitted within the appropriate time frame.

espectfully submitted,

Manager, Nuclear Operations

RJR:HH:jr

1003/10

8003040569