

**EBASCO SERVICES INCORPORATED**Materials Engineering Laboratory, Bldg. 100A Port Kearny  
South Kearny, New Jersey 07032

September 16, 1980

Director, U.S.N.R.C.  
Office of Inspection and Enforcement  
631 Park Avenue  
King of Prussia, PA 19406


Reference: Docket #030-05323  
Control #02465  
Lic. No. 29-07056-03

Dear Sirs:

In accordance with IE bulletin No. 80-22 we reply the following:

1. No Action Required - we exclusively use technical operation equipment in which direct positive action is required for disconnect.
2. No Action Required - see above.
3. The bulletin and IE circular No. 79-16 have been scheduled to be reviewed at the next safety meeting.
4. No Action Required - see (1).
5. This item, with us, is a continuous discussion with all our radiographers and will continue to be, but not to the point of overkill.

Sincerely,



A. S. Fantini  
Assistant Radiation Protection Officer

ASF/amw

cc: Director, Division of  
Fuel Facility and  
Material Safety Inspection

**EBASCO**

8010210230