

Continuation of LER Report

will include the results of the radiography and stress analyses, and the schedule for repairing or replacing the piping as necessary. The affected piping is 8", schedule 40, 304SS at 55 psig/100^oF borated water conditions.