

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

March 20, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Procedure Inadequacy - MSIV Maintenance

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.f. Procedural controls were not adequate to prevent fuel moves during main steam line isolation valve maintenance.

Yours very truly,

David M usoff FOM

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/ak

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

8003250403