

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5		
	LICENSEE CODE						LICENSEE NUMBER																LICENSE TYPE						CAT 58

CON'T

0 1	L	6	0	5	0	-	0	2	9	3	7	0	3	1	0	8	0	8	0	4	0	9	8	0	9
	REPORT SOURCE			DOCKET NUMBER					EVENT DATE					REPORT DATE											

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | Hydrant Hose House No. 5 was damaged when hit by a truck. The house was wrapped

0 3 | around the Hydrant preventing access to it. The house was rebuilt and returned

0 4 | to service.

0 5 |

0 6 |

0 7 |

0 8 |

0 9	A	B	11	X	12	Z	13	X	X	X	X	X	X	14	X	15	Z	16	17	8	0	—	0	1	0	/	0	3	L	—	0
	SYSTEM CODE			CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			LER/RO REPORT NUMBER	EVENT YEAR			SEQUENTIAL REPORT NO.	OCURRENCE CODE	REPORT TYPE	REVISION NO.							
1 0	X	18	C	19	Z	20	Z	21	0	0	0	22	N	23	N	24	A	25	Z	9	9	9	26								
	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER																					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

1 0 | Additional hose was strung from Hydrant Hose Station No. 3 to protect areas

1 1 | normally covered by Hydrant Hose Station No. 5.

1 2 |

1 3 |

1 4 |

1 5	H	28	0	0	0	29	N.A.	30	A	31	Operational Event	32
	FACILITY STATUS	% POWER	OTHER STATUS				METHOD OF DISCOVERY	DISCOVERY DESCRIPTION				
1 6	Z	33	Z	34	N.A.	35	N.A.	36				
	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
1 7	0	0	0	37	38	N.A.	39					
	PERSONNEL EXPOSURES		DESCRIPTION									
1 8	0	0	0	40	N.A.	41						
	PERSONNEL INJURIES		DESCRIPTION									
1 9	Z	42	N.A.	43	N.A.	44						
	LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION									
2 0	N	45	N.A.	46								
	PUBLICITY ISSUED	DESCRIPTION										

8004140 342