

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

3780 3 29:29

March 31, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE UNIT B-1 AND PHIPPS BEND UNIT 1 NUCLEAR PLANTS - REPORTABLE DEFICIENCY - RADIOGRAPHIC EXAMINATION OF HARTSVILLE DRYWELL VENT STRUCTURE AND PHIPPS BEND RPV PEDESTAL - WELD BUILDUP MADE AND EVALUATED IMPROPERLY (NCR S-7 AND S-13)

Initial notification of the subject deficiencies was made to R. W. Wright of your staff on January 15, 1980. The final report was submitted by letter from me to you dated February 15, 1980. As requested by Mr. Wright on March 25, 1980, enclosed is a revision to the corrective actions identified in the February 15, 1980, report. This revision to the final report is filed to correct an inconsistency between the corrective action stated in the report and the corrective action approved by the Technical Engineer to correct defects in the drywell vent structure at the Hartsville Nuclear Plant. All other items in the final report are unchanged. If you have any additional questions concerning this subject, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

A002
S
1/1