

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

TIC
50-327
338
005200273

April 29, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Enclosed is a report which discusses the problem of incorrect pipe stresses calculated (per IE Bulletin 79-14) by the TPIPE computer program. The problem is generic to our Browns Ferry, Sequoyah, Watts Bar, and Bellefonte Nuclear Plants IE Bulletin 79-14 evaluations. Corrective actions, which TVA is taking to rectify the problem, are also discussed in the enclosure.

The enclosed information was requested by Leo Modenos of your staff during a March 19 and 20, 1980, inspection at our Knoxville offices. If you have any questions, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

OFFICIAL COPY