



LER SUPPLEMENTAL INFORMATION

SQRO-50-327/ 8033      Technical Specification Involved 3.1.2.3

Reported Under Technical Specification 6.9.1.13.c

Date of Occurrence: 4/11/80      Time of Occurrence: 0940 CST Unit 1

Identification and Description of Occurrence:

CCP 1-A was removed from service and CCP 1-B placed in service with D/G 1-B out of service. With D/G 1-B out of service, CCP 1-B was being powered, by definition, from an inoperable shutdown board, even though its normal and alternate supplies were operable.

Conditions Prior to Occurrence:

Unit 1 in Mode 6 with all fuel loaded and reactor head on and no Core Alterations being performed.

Apparent Cause of Occurrence:

Personnel did not verify D/G operable on the shutdown board from which the CCP was being powered during Mode 6.

Analysis of Occurrence:

There was no hazard to the public health and safety.

Corrective Action:

Personnel was instructed as to the requirements of LCO 3.1.2.3.

Failure Data:

N/A