

LER NO. 80-25/3L
DOCKET NO. 50-318
EVENT DATE 04/28/80
REPORT DATE 05/16/80
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

THE CHANNEL A RPS FLOW SIGNAL WAS NOT AFFECTED. NO PREVENTIVE ACTION IS DEEMED NECESSARY AT THIS TIME.