

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057 TELEPHONE 717-244-4041

June 17, 1974

DK Central file

Mr. J.P. O'Reilly, Director
Directorate of Regulatory
Region I
631 Park Avenue
King of Prussia, Pa. 19406

POOR ORIGINAL

Operating License DPR-50
Docket 50-283

Subject: Abnormal Occurrence No. AD 74-77

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Lee Spessard (Region I-AEC), and J.G. Herbein (THI-Superintendent) at 1330 HRS. 14 June 1974.

The following report is submitted in accordance with paragraph 5.7.2.a. 2 (page 5-11) of the Technical Specifications.

On 13 June both doors of the Reactor Building Personnel Access Hatch were opened simultaneously while the reactor coolant system temperature and pressure were at 532° and 2155 psig.

The inner door of the Reactor Building Personnel Access Hatch was inadvertently left open, during personnel egress, when a connecting pin sheared on the door operating mechanism drive shaft.

As a result of the sheared pin, the double door mechanical interlock was rendered inoperable.

The inner Reactor Building Access Hatch door was immediately closed and the mechanical interlock was made operable by replacing the sheared connecting pin on the door operating mechanism drive shaft.

Very truly yours,

J.G. Herbein

J.G. Herbein
Station Superintendent
THI Nuclear Station

JGH/dmm

M/D

7910250 631

5