

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-944-4041

June 6, 1974

Mr. J.P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pa. 19406

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No. AD 74-7

POOR
ORIGINAL

Dear Mr. O'Reilly:

This telegram is to confirm a conversation between L. Spessard (Region I-CRO), and J.G. Herbein (TMI Superintendent) at 1630 HRS. 5 June 1974.

The following report is submitted in accordance with paragraph 6.7.2.a.5 (page 6-11) of the Technical Specifications.


On 4 June 1974 previous revisions of valve checklists and startup checklists of 15 currently revised operating procedures were found to have been used during the course of plant startup. At 1615 HRS. 5 June 1974 the Plant Operations Review Committee evaluated the occurrence as an observed inadequacy in the implementation of administrative controls during the operation of the facility which could effect the safety of operations.

At the time of the finding the primary plant was at 5320F, 2155 psig and preparations were in progress for initial criticality.

The specific differences between the current revisions and previous revisions of the respective checklists were researched and no unsafe conditions were found to exist as a result of using the outdated checklists.

All the revised valve lineups were verified in the plant to assure they were positioned properly in accordance with the current procedures and administrative steps are being taken to preclude similar administrative errors.

Very truly yours,


J.G. Herbein
Station Superintendent
TMI Nuclear Station

JGH/dan

10250685

5