


Dk Central Files



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

DOT OFFICE BOX 410 MIDDLETOWN, PENNSYLVANIA 17057 TELEPHONE 717-944-4011

December 2, 1974

POOR ORIGINAL

Mr. J.P. O'Reilly, Director
Directorate of Regulatory
Division I
691 Park Avenue
King Of Prussia, Pa. 19603

Operating License DPR-50
Docket 50-200

Subject: Abnormal Occurrence No. AO 74-25

Dear Mr. O'Reilly:

This telegram is to confirm the discussion between Lee Spassard (Region I-AEC), and J.G. Herstein (TII-Station Superintendent) at 1900 hours 29 November 1974.

The following report is submitted in accordance with paragraph 6.7.2.a.4 (page 6-11) of the technical specifications.

Inspection of the ID Engineered Safeguards Motor Control Center DS-50 feeder breaker, due to periodic breaker trips, revealed mechanical binding of the plunger on the A phase overcurrent device.

The binding of the plunger caused premature breaker trip when control center supply current exceeded 1000 amps.

The A phase overcurrent device was replaced on the ID Engineered Safeguards Motor Control Center feeder breaker. The breaker was tested satisfactorily and returned to normal operation.

Very truly yours,

J.G. Herstein
J.G. Herstein
Station Superintendent

JCH:dmr

7910260466

5