



## METROPOLITAN EDISON COMPANY

POST OFFICE BOX 480 MIDDLETOWN PENNSYLVANIA 17057 TELEPHONE 717-244-4011

21 October 1976

Mr. J. P. O'Reilly  
 Directorate of Regulatory Operations  
 Region I  
 Nuclear Regulatory Commission  
 631 Park Avenue  
 King of Prussia, Pennsylvania 19406

**POOR ORIGINAL**

Operating License CPR-00  
 Docket 50-289

Subject: Reportable Occurrence No. 76-37/1P

Dear Mr. O'Reilly:

This telegram is to confirm the telephone conversation between Mr. Lee Scessard (Region 1-NPC) and Mr. J. J. Colitz (TMI-1 Unit Superintendent) at 1315 hours on 21 October 1976.

The following report is submitted in accordance with Paragraph 6.9.A.(2) of the Technical Specifications.

An apparent violation of Technical Specification 3.5.2.5.a occurred in that the indicated overlap between Group 6 and Group 7 was thirty-two (32%) percent as evidenced by the hourly computer printout.

The normal overlap was not maintained because of a blown control fuse for the Group 6 programmer. Group 6 was transferred to the auxiliary power supply and the overlap condition was corrected.

The reactor was operating at a reduced power level and imbalance and rod index were well within the required limit.

The procedural guidance given for operation with a sequence fault

1589 342

7911010 707 S

Mr. J. P. O'Reilly

-2-

21 October 1976

is being evaluated. Additional information will be provided in the fourteen (14) day follow-up report.

Very truly yours,

*J. J. Colitz*

J. J. Colitz

Unit I Superintendent

Three Mile Island Nuclear Station

JJC/pas

POOR ORIGINAL

1589 343