

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSER CODE: SCNEE1 DOCKET NUMBER: 05010000000-0003411111 CAT 58

REPORT SOURCE: L95010026970110578801323789

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 During normal operation Keowee Hydro Unit 2 failed to start on initiation from Oconee control room. Since Keowee 2 is a source of auxiliary power for the Oconee station (Units 1, 2, and 3) this is reportable under T. S. 6.6.2.1.b.(2). The unit started normally on second and subsequent attempts.

SYSTEM CODE: EE CAUSE CODE: X CAUSE SUBCODE: X COMPONENT CODE: Z Z Z Z Z Z VALVE SUBCODE: Z COMP. SUBCODE: Z REPORT TYPE: L REVISION NO: 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 The Field Flashing Breaker (DB-26) on the generator failed to close on first attempt. The breaker was verified as operable by subsequent operation and visual examination. Inspection and servicing resulted in no further corrective action. Extensive investigation is continuing as of March 23, 1978.

FACILITY STATUS: E POWER: 110 OTHER STATUS: NA METHOD OF DISCOVERY: A DISCOVERY DESCRIPTION: Operator Observation

ACTIVITY CONTENT: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES: 000 DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY: Z DESCRIPTION: NA

PUBLICITY ISSUED: N DESCRIPTION: NA

NAME OF PREPARER: K. R. Wilson PHONE: (704) 373-8197

7912110752