

LICENSEE EVENT REPORT

CONTROL BLOCK: _____
1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME F L C R P 3			LICENSE NUMBER 0 0 - 0 0 0 0 - 0 0					LICENSE TYPE 4 1 1 1 1			EVENT TYPE 0 1				
CATEGORY 0 1 CONT		REPORT TYPE 0 0		REPORT SOURCE L		DOCKET NUMBER 0 5 0 - 0 3 0 2				EVENT DATE 1 2 1 7 7 6			REPORT DATE 0 2 0 2 7 7		

EVENT DESCRIPTION

02 | During trouble shooting of Emergency Safeguards Actuation System, high pressure injection was inadvertently actuated. System drawing error was cause and appropriate design change request has been initiated. Because of RC System condition, this is considered to be the zero (0) cycle HPI.
06 | (77-7)

SYSTEM CODE S F		CAUSE CODE B		COMPONENT CODE I N S T R U				PRIME COMPONENT SUPPLIER A		COMPONENT MANUFACTURER X X X X				VIOLATION N	
----------------------	--	-----------------	--	---	--	--	--	-------------------------------	--	---	--	--	--	----------------	--

CAUSE DESCRIPTION

08 | Design drawing showed incorrect channel designation. Design change has been requested to correct channel feed designation.

FACILITY STATUS B		% POWER 0 0 0			OTHER STATUS Mode 5			METHOD OF DISCOVERY A		DISCOVERY DESCRIPTION Alarm				
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY N/A			LOCATION OF RELEASE						

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
		N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION
	N/A

OFFSITE CONSEQUENCES

15 | N/A

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
	N/A

PUBLICITY

17 | N/A

ADDITIONAL FACTORS

19 | N/A

8002270591

NAME: W. P. Stewart *WPS*

PHONE: (813) 866-4159