



4 January 1977
CS-77-1
3-0-3-a-2

Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree St., N.W., Suite 818
Atlanta, Georgia 30303

Docket No. 50-302
License #DPR-72

Dear Mr. Moseley:

In response to the infraction noted in Inspection and Enforcement Report No. 50-302/76-22, non-compliance 76-22-A1(II), we offer the following.

Infraction - Failure to Evaluate Examination Data

"Contrary to 10 CFR 50.55a and Article 1S-300 of the ASME Code, Section XI, Winter 1972, the licensee failed to evaluate an indication in the baseline data that exceed acceptable standards of ASME Section III when performing the preservice inspection."

The corrective steps which we have taken include formal request to have those items noted in your Inspection Report reviewed by the Contractor Level 3 Examiner. This was done, and the disposition of these items was that they were not code rejectable.

The corrective steps we have taken to avoid further non-compliances include a request for review of the Baseline Report to assure that any other indication of this nature had not been overlooked. This review by the Contractor did identify a small number of non-code rejectable indications which have now been so designated.

Full compliance has been achieved as of this date.

If there are further questions, please contact us.

No proprietary information has been identified in Inspection Report 50-302/76-22.

Very truly yours,

FLORIDA POWER CORPORATION

W. P. Stewart

W. P. Stewart
Director, Power Production

DWP/feh

[Signature]
Nuclear Plant Manager

8002 270739