



SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/77-87

2. Facility: Crystal River Unit #3

3. Report Date: 8 August 1977

4. Occurrence Date: 15 July 1977

5. Identification of Occurrence:

Containment isolation valve WDV-94 was inoperable contrary to Technical Specification 3.6.3.1.

6. Conditions Prior to Occurrence:

Mode 1 power operation.

7. Description of Occurrence:

At 0700, while performing the quarterly cycling of valves Surveillance Procedure SP-370, valve WDV-94 failed to operate. The 4 hour action statement was entered. Maintenance was performed and valve restored operable within 4 hours.

8. Designation of Apparent Cause:

This event was due to the limit switch contacts being dirty. The contacts were cleaned and valve restored operable.

9. Analysis of Occurrence:

There was no safety implications due to this event, as a redundant waste disposal valve was used to isolate the system.

10. Corrective Action:

None required as normal maintenance restored the valve's operability.

11. Failure Data:

This was the first time valve WDV-94 had failed to operate..