

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-016/04L-0
2. Facility: Crystal River Unit #3
3. Report Date: 31 May 1978
4. Occurrence Date: 4 April 1978 (discovered 16 May 1978)
(determined at plant 31 May 1978)

5. Identification of Occurrence:

Contrary to Environmental Technical Specification 3.1.5, a sample was not obtained from test well 5 for the months of April and May.

6. Conditions Prior to Occurrence:

N/A

7. Description of Occurrence:

The April and May samples from test well 5 were not collected because the well had been inadvertently covered during construction in the area.

8. Designation of Apparent Cause:

While repairing a pipe break in the area, debris was placed on top of test well 5. The well is only a pipe that extends about one foot above the ground. During cleanup after the repair, the debris and the well were leveled.

9. Analysis of Occurrence:

The closing of the well did not result from operation of Crystal River Unit #3 nor is operation of the plant affected by it.

10. Corrective Action:

Upon discovery, measures were instituted to ensure that the well would be available for sampling in June (as the sampling period for May had already passed). The well was re-established for sampling on 26 May 1978. In addition, markers will be attached to the well for higher visibility to preclude this type of accident in the future.

11. Failure Data:

This is the first report for this type occurrence.

8002 280 972