

Houston
Lighting
& Power
Company

Electric Tower
P.O. Box 1700
Houston, Texas 77001

February 12, 1980

ST-HL-AE-418
SFN: C-0570

Mr. W. C. Seidle
Reactor Construction and
Engineering Support Branch
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

SUBJECT: SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION
RESPONSE TO NRC INSPECTION FINDINGS
DOCKET NOS. 50-498/79-15 AND 50-499/79-15

Dear Mr. Seidle:

The following is the additional information you requested on the item of noncompliance identified in IE Inspection Report Nos. 50-498/79-15 and 50-499/79-15 and addressed in your letter of January 24, 1980.

Failure to Follow Concrete Consolidation Procedure

Corrective Action

The concrete placement identified in your Inspection Report 79-15 was re-vibrated satisfactorily to the Resident Reactor Inspector as stated in your letter of January 24, 1980.

Recurrence Control

Brown & Root Construction has established a requirement for all vibrator operators to be retrained every 90 days on the basis of current procedures, including Brown & Root Procedure CCP-4.


8004070069

Mr. Seidle
February 12, 1980
Page Two

Date Action to be Completed

All reinstruction of current vibrator personnel will be completed by February 21, 1980.

Very truly yours,



E. A. Turner, Vice President
Power Plant Construction
& Technical Services

EAT:rka

cc: Messrs. G. W. Oprea, Jr.
R. A. Frazar
D. G. Barker
M. L. Borchelt (CPL)
C. G. Thrash (CPL)
J. B. Poston (CPS)
R. C. Mecke (CPS)
R. L. Hancock (COA)
M. C. Nitcholas (COA)
T. D. Stanley
L. D. Wilson
G. B. Painter
M. D. Schwarz (Baker & Botts)
H. S. Phillips (NRC)
J. R. Geurts (B&R)
C. W. Vincent (B&R)
STP RMS