

## (7-77)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8	
7	8	9

17 LER/RO  
REPORT  
NUMBER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7	8	9
---	---	---

1	5
---	---

1	6		
---	---	--	--

1	7
---	---

181

1	2
---	---

155	1
-----	---

PHONE

919-457-9524 70 337

LER ATTACHMENT - RO #2-80-034

Facility: BSEP Unit # 2

Event Date: March 7, 1980

The problem with the pipe clamp slipping has been identified on other snubbers in past inspections. Our maintenance engineers are in contact with the manufacturer to determine a method to prevent slippage.