LICENSEE EVENT REPORT

•	CONTROL BLOCK:
01	P A B V S 1 2 0 0 - 0 0 0 0 - 0 0
CON'T	REPORT L 6 0 5 0 0 0 3 3 4 7 0 3 1 2 8 0 3 0 3 1 1 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (1)
0 2	The emergency shutdown panel Auxiliary Feedwater Flow instrumentation readings were
0 3	deleted from surveillance testing due to the meter indication always reading zero,
0 4	during power operation. There were no implications to the health and safety of the
0 5	general public because the shutdown panel was not needed or used.
0 6	
0 7	
0 8	80
7 8 0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	The surveillance test reading was removed from the data sheet because, during power
	operation, the meter always reads zero when Auxiliary Feedwater is in standby. In
1 2	the future, the flow indicator checks will be done during startup when the pumps are
13	tested for operability.
14	80
1 5	ACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 N/A C 31 Operations audit
	CIVITY CONTENT SLEASED OF RELEASE AMOUNT OF ACTIVITY (35) AMOUNT OF
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O TO T
	PERSONNEL INJURIES NUMBER DESCRIPTION (4) N/A DMMD MD MD MD M 80
1	TYPE DESCRIPTION N/A N/A N/A
	PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY
*	NAME OF PREPARER J. A. Werling PHONE 412-643-1258
	8004070346