

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: P A B V S 1; LICENSE NUMBER: 00-000000-000; LICENSE TYPE: 41111; CAT: 58

REPORT SOURCE: L; DOCKET NUMBER: 05000334; EVENT DATE: 031280; REPORT DATE: 033180

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

The emergency shutdown panel Auxiliary Feedwater Flow Instrumentation readings were deleted from surveillance testing due to the meter indication always reading zero, during power operation. There were no implications to the health and safety of the general public because the shutdown panel was not needed or used.

SYSTEM CODE: CH; CAUSE CODE: D; CAUSE SUBCODE: Z; COMPONENT CODE: ZZZZZZ; COMP SUBCODE: Z; VALVE SUBCODE: Z; LER-RO REPORT NUMBER: 80; EVENT YEAR: 80; SEQUENTIAL REPORT NO.: 012; OCCURRENCE CODE: 01; REPORT TYPE: T; REVISION NO.: 0; ACTION TAKEN: G; FUTURE ACTION: Z; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRD-4 FORM SUB: N; PRIME COMP SUPPLIER: Z; COMPONENT MANUFACTURER: Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The surveillance test reading was removed from the data sheet because, during power operation, the meter always reads zero when Auxiliary Feedwater is in standby. In the future, the flow indicator checks will be done during startup when the pumps are tested for operability.

FACILITY STATUS: H; POWER: 0000; OTHER STATUS: N/A; METHOD OF DISCOVERY: C; DISCOVERY DESCRIPTION: Operations audit

ACTIVITY RELEASED OF RELEASE: Z; AMOUNT OF ACTIVITY: N/A; LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES NUMBER: 000; TYPE: Z; DESCRIPTION: N/A

PERSONNEL INJURIES NUMBER: 000; DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY TYPE: Z; DESCRIPTION: N/A

PUBLICITY ISSUED DESCRIPTION: N

NAME OF PREPARER: J. A. Werling

PHONE: 412-643-1258

8004070346

POOR ORIGINAL