

BOSTON EDISON COMPANY
GENERAL OFFICES 800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

G. CARL ANCONINI
SUPERINTENDENT
NUCLEAR OPERATIONS DEPARTMENT

April 1, 1980

BECO Ltr. #80-51

Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License No. DPR-35
Docket No. 50-293

Dear Sir:

In a telecon on 3/27/80 you requested information relative to unscheduled entries of the drywell for the time frame 1/1/75 to present. Due to the manpower commitments surrounding the ongoing refueling outage effort, it was only possible to obtain the requested information from 8/1/77 to the present.

Response

1. A table is attached listing the requested data.
2. There have been no provisions considered to detect and reduce RCS leakage without entry beyond the originally installed monitoring equipment and equipment installed in response to NUREG 0578.
3. The plant did not operate with RCS leakage in the containment during the researched time period.

We hope the information provided is responsive to your needs and if you have any further questions please contact us.

Very truly yours,

G. Carl Anconini

A001
5
1/1

8004080398

Response to Item 1

<u>Date of entry</u>	<u>Reason for Entry</u>	<u>Duration of Shutdown</u>	<u>Results</u>
4/78	Inboard MSIV disk stem separation	178 hours	Valve repaired
10/78	Relief Valve Malfunction	438 hours	Valve repaired
3/79	SRM/IRM Malfunction	111 hours	Repaired
6/79	Relief Valve Leaking	40.1 hours	Repaired
7/79	MSIV Timing Out of Specs	28.2 hours	Retimed
7/79	Relief Valve Malfunction	85.5 hours	Repaired