



HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

6TH AVENUE AND PINE STREET • PINE BLUFF, ARKANSAS 71601 • (501) 534-1330

August 29, 1974

United States Atomic Energy Commission  
Directorate of Regulatory Operations  
Region II  
230 Peachtree Street, N.W., Suite 618  
Atlanta, Georgia 30303

Attention: Mr. Norman C. Moseley, Director

Subject: Arkansas Power & Light Company  
Arkansas Nuclear One - Unit 1  
RO:II:MSK 50-313/74-10

Gentlemen:

We are submitting this as a supplement to our previous response, dated August 13, 1974, to the apparent violations as detailed in the above report.

- 1.A.1.a "Procedure Review of Special Processes"  
Procedure 1701.01, "Repair of Incore Instrument Tubes" has been reviewed by the QCE on 8/6/74 and Technical Support Engineer on 8/7/74 with no deficiencies noted. Procedure No. 1005.02, "Handling of Procedures", has been revised as of 6/10/74. As per this revision, any special procedures covered under 1004.07, "Control of Special Processes", will be forwarded to the cognizant supervisor for review by the Plant Safety Committee Secretary before the final approval and implementation.
- 1.A.1.c "Failure to Log Significant Annunciations"  
The revision to 1005.01 "Administrative Control Manual" as noted in our previous response has been signed by the Plant Superintendent and implemented as of 8/5/74.
- 1.A.2.b "Failure to Document Inspection of Socks Placed Over The Ends of Incore Tube Nozzles to Accumulate Cuttings During Flushing"


COPY SENT TO: PDR ✓  
LPDR ✓  
NSIC ✓  
TIC ✓

8004110 757

August 29, 1974

An inspection report was prepared on August 23, 1974 to document the fact that we did inspect the shavings, but there was no way to make any definite conclusions from the inspection. In lieu of the inspection of shavings, the integrity of the incore tubes was assured by hydrotest to 4,000 psi.

Very truly yours,



J. D. Phillips  
Senior Vice President

JDP:mb