



LER SUPPLEMENTAL INFORMATION

SQRO-50-327/ 8026      Technical Specification Involved 3.3.3.9

Report Under Technical Specification 6.9.1.13.b

Date of Occurrence: 3/17/80      Time of Occurrence: 1130 CST      Unit 1

Identification and Description of Occurrence:

ERCW Effluent Line Monitors (O-RE-90-134, 141) were declared inoperable while maintenance was performed on the flow switch which provides the low flow alarm.

Conditions Prior to Occurrence:

Unit 1 in Mode 6 with all fuel loaded.

Apparent Cause of Occurrence:

The flow switch providing the low flow alarm was dirty and would not perform its function until it was cleaned.

Analysis of Occurrence:

There was no hazard to the public health or safety.

Corrective Action:

The flow switches were cleaned and a PMI periodically checks them.

Failure Data:

N/A