



LER SUPPLEMENTAL INFORMATION

SQRO-50-327/8027      Technical Specification Involved      N/A

Reported Under Technical Specification 6.9.1.13.c

Date of Occurrence: 3/18/80      Time of Occurrence: 1500 CST      Unit 1

Identification and Description of Occurrence:

The NRC found FCV-26-240, 241, 242, 243, 244, and 245 closed during a walkdown. Evidently, a Phase A isolation signal closed these valves sometime in the past and SOI-88.1 (the recovery procedure) did not call for them to be reopened. They provide fire protection water to the annulus and RCP's.

Conditions Prior to Occurrence:

Unit 1 in Mode 6 with all fuel loaded.

Apparent Cause of Occurrence:

Procedure deficiency.

Analysis of Occurrence:

There was no hazard to public health or safety.

Corrective Action:

Valves were opened immediately. A temporary change was written for the recovery procedure until the procedure can be revised.

Failure Data:

N/A