

8005020262

Plant E. I. Hatch
PM-80-455
April 24, 1980
Special Report
Docket No. 50-366

HPCI INJECTION INTO REACTOR

At 0620 on 2-6-80 HPCI was manually started and injected into the Reactor vessel to maintain Reactor vessel water inventory following trip of the Reactor feed pump. Only one Reactor feed pump was running and it tripped on low vacuum because the Reactor feed pump loop seal was lost. RCIC was also injecting during this time but it was not adequate under the conditions to maintain proper water level. HPCI was shutdown and returned to standby condition at 0742. It was operated for (1) hour and 22 minutes.

As of the date of this report there have been (10) HPCI injections into the Reactor vessel.