



8005020366

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

March 24, 1980

Mr. R. F. Heishman, Chief
Reactor Operations and Nuclear Support Branch
Region III, Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Heishman:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT

Docket Nos. 50-282 and 50-306

In response to your letter of March 3, 1980, which transmitted Inspection Reports No. 50-282/80-01 and 50-306/80-01, the following is offered:

The event which resulted in the infractions was discussed with members of your office on February 26, 1980. Corrective Actions taken are as described in the Inspection Reports and the Licensee Event Report for RO 80-1. Corrective Actions were:

1. Revision to the section work instruction SWI-0-10, Use of the Operations Manual, dated January 8. The revision requires that for procedures that are applicable to either unit, the valve and numbers and parameters that are not applicable to the unit on which the procedure is to be performed shall be designated by drawing a line through them.
2. Revision to SWI-0-3, Safeguards Hold Cards and Component Blocking or Locking, dated January 7, 1980. The revision requires that installation and removal of Safeguards Hold Tags shall be logged and that any removed lock or block and its safeguards hold tag shall be delivered to the Shift Supervisor immediately.
3. The event and its significance were discussed with the individuals involved.

It is felt full compliance has been achieved at this time.

Yours truly,

D. E. Gilberts
Vice President
Power Production

DEG:nk

cc: Mr. G. Charnoff

APR 1 1980