

NSP

8005060 A255

5

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 30, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42
50-306 DPR-60

Missed Surveillance Test

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification Section 6.7.B.2(c) in that there was an inadequacy in the implementation of administrative controls which might have affected the degree of battery redundancy if the individual float cell voltage measurements had been unsatisfactory. Subsequent measurements indicated individual float cell voltages were satisfactory for the period missed.

Yours very truly,


L O Mayer, PE
Manager of Nuclear Support Services

LOM/JAG/ak

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

A002
S
//