

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

Central file
50-269
50-
287

May 25, 1978

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Suite 1217
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

RE: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

In response to your letter of April 14, 1978, which forwarded IE Bulletin 78-05, a review of the design of Oconee Nuclear Station has been performed. The results of this review indicate that there are no GE CR105X auxiliary contact mechanisms in use in safety-related equipment at Oconee.

Very truly yours,


William O. Parker, Jr.

RLG:scs

cc: Director, Division of Reactor Operations Inspection

704
7912130 864 Q