

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Hartsville 1

License Nos. CFPR-150

Based on the NRC inspection December 11-14, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50, and as implemented by PSAR Section 17.1a.5, "Activities affecting quality shall be prescribed by documented instructions, procedures, ... and shall be accomplished in accordance with those instructions, procedures, ...". TVA Procedure SOP-34 Revision 1, requires that prior to the commencing of welding ... the welding inspector shall verify that the proper preheat is being used ... and shall record this on the weld operation check list.

Contrary to the above, on December 12, 1979, preheat inspection had been signed off for weld DVS00035 at a time when the welder was not ready to commence welding.

This is an infraction.

8008190 785