



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
230 PEACHTREE STREET, N.W. SUITE 818
ATLANTA, GEORGIA 30303

Report No.: 50-269/78-03, 50-270/78-03 and 50-287/78-03

Docket Nos.: 50-269, 50-270 and 50-287

License Nos.: DPR-38, DPR-47 and DPR-55

Licensee: Duke Power Company
422 S. Church Street
Charlotte, North Carolina 28242

Facility Name: Oconee Units 1, 2 and 3

Inspection at: Oconee site, Seneca, South Carolina

Inspection conducted: February 8-10, 1978

Inspector: W. H. Bradford

Reviewed by: C. E. Alderson
C. E. Alderson, Acting Chief
Nuclear Support Section No. 2
Reactor Operations and Nuclear Support Branch

2/24/78
Date

Inspection Summary

Inspection on February 8-10, 1978 (Report Nos. 50-269/78-03, 50-270/78-03 and 50-287/78-03)

Areas Inspected: Routine, unannounced inspection of quality assurance program annual review and licensed operator requalification training program. The inspection involved 24 inspector-hours on site by one NRC inspector.

Results: Of the two areas inspected no items of noncompliance or deviations were found.

7911280 696

DETAILS I

Prepared by: W. H. Bradford
W. H. Bradford, Reactor Inspector
Nuclear Support Section No. 2
Reactor Operations and Nuclear
Support Branch

2/22/78
Date

Dates of Inspection: February 8-10, 1978

Reviewed by: C. E. Alderson
C. E. Alderson, Acting Chief
Nuclear Support Section No. 2
Reactor Operations and Nuclear
Support Branch

2/24/78
Date

1. Individuals Contacted

Duke Power Company

- *J. Ed Smith, Station Manager
- *J. N. Pope, Superintendent of Operations
- J. T. McIntosh, Director of Administrative Services
- *O. S. Bradham, Superintendent of Maintenance
- *Roger Nichols, Administrative Assistant/Training and Safety
- *R. T. Bond, Technical Services Engineer
- Richard Bugert, Training Coordinator
- *R. J. Brackett, QA Senior Engineer
- D. C. Dukes, QA Audit Supervisor

*Denotes those present at exit interview.

2. Licensee Action on Previous Inspection Findings

Not inspected.

3. Unresolved Items

None identified during this inspection.

4. Exit Interview

The inspector met with licensee representatives (denoted in paragraph 1) at the conclusion of the inspection on February 10, 1978. The inspector summarized the scope and findings of the inspection.

5. Licensed Operator Requalification Training

The inspector reviewed licensee documents to verify that a requalification training program for NRC licensed reactor operators (ROs) and senior reactor operators (SROs) had been established and was consistent with the requirements of the licensee's approved Requalification Program, Section 6.1.1.5 of the Technical Specifications, and Appendix A to 10 CFR 55. The inspector reviewed individual training records for twelve licensed operators and held discussions to determine whether the program had been implemented. Within the areas inspected, no items of noncompliance or deviations were identified.

6. Quality Assurance Program Review

The inspector reviewed the licensee's QA Program to determine whether recent changes to the program were in conformance with Appendix B to 10 CFR 50, as well as applicable codes, standards, guides and licensee commitments. Within the areas inspected, no items of noncompliance or deviations were disclosed.

The Duke Power Company Quality Assurance Program changes over the past year consisted of revisions to reflect organizational changes and responsibilities to add 10 CFR 21 evaluations and reporting requirements and to define frequency of audits. The inspector had no further questions.