

ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 20, 1980

2-050-14

Mr. K. V. Seyfrit, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6

Licensee Event Report No. 80-022/03L-0

(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9b, attached is the subject report concerning the Emergency Feedwater Pump (EFP) turbine (2K3) for pump $\angle P7A$, which tripped on overspeed due to low steam generator level.

Very truly yours,

David C. Trimble

David C. Trimble Manager, Licensing

DCT:GAC:skm

Attachment

cc: Mr. Victor Stello, Jr., Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555