LICENSEE EVENT REPORT

| CONTROL BLOCK: | (PLEASE PRINT ALL REQUIRED INFORMATION) |
|--|---|
| LICENSEE LICENSE NUMBER | UCENSE EVENT TYPE TYPE |
| 7 89 14 15 000000000000000000000000000000000 | 4 1 1 1 1 0 1 26 30 31 32 |
| CATEGORY TYPE SOURCE DOCKET NUMBER 7 8 57 58 59 60 61 68 69 | 2 4 7 7 0 8 2 9 7 7 7 7 7 7 7 7 7 |
| EVENT DESCRIPTION [0] While performing the refueling interval diesel generate | or SFAS start and load |
| 7 8 9 O3 sequencing surveillance on August 24, 1977, diesel gen | erator B failed to start. After |
| 04 unsuccessfully checking for the cause, a restart was m | |
| OS completed. The redundant generator was available duri | ng the occurrence. Similar 30 |
| [0] [failures have occurred in the past, most recently on 9 | |
| SYSTEM CAUSE CODE COMPONENT CODE SUPPLER MANUFACTURE O 7 B 9 10 11 12 17 43 44 | |
| CAUSE DESCRIPTION No specific cause could be determined. The biannual i | nspection and overhaul of the |
| og engine, air start motors, and governor is being perfor | med during the refueling outage, |
| which will eliminate any existing problems. | 30 |
| FACILITY STATUS OTHER STATUS OSCOVERY O | NA DISCOVERY DESCRIPTION 80 |
| FORM OF ACTIVITY CONTENT OF RELEASE AMOUNT OF ACTIVITY 1 2 Z Z NA 10 11 44 45 PERSUNNEL EXPOSURES | NA LOCATION OF RELEASE |
| 7 8 9 11 12 13 | 90 |
| PERSONNEL INJURIES NUMBER DESCRIPTION 114 00 0 0 NA | |
| 7 8 9 11 12 OFFSITE CONSEQUENCES | 80 |
| Minimal to none | |
| LOSS OR DAMAGE TO FACILITY TYPE DESCRIPTION | 80 |
| 7 8 9 10 NA | 80 |
| PUBLICITY 17 Local newspapers and wire services notified August 29, | 1977. |
| ADDITIONAL FACTORS | |
| The "B" diesel generator is a Bruce GM Diesel, Inc. un | 8002210592 80 |
| 19 (serial number 17002011-200). | 90 |
| NAME: R. W. Colombo/F. T. Eisenhuth | PHONE: (916) 452-3211 |