Notice of Violation

Sacramento Municipal Utility District Sacramento, California Docket No. 50-312

Based on the results of an NRC inspection conducted on March 29 - April 1, 1976 it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below.

- Contrary to Technical Specification 6.5.2 the Management Safety Review Committee had not performed certain review and reporting functions as follows:
 - a. Records do not show that the Committee had reviewed and advised the General Manager on the violation identified by the NRC in June 1975 partaining to the failure to implement Administrative Procedure No. 26, "Control of Bypasses and Jumpers."
 - b. The minutes for the MSRC meeting of February 27, 1976 were not prepared, approved and distributed within 14 days.

This item is a deficiency.

2. Contrary to Technical Specification 4.4.1.4, a visual examination has not been made annually of the accessible interior and exterior surfaces of the containment structure and its components to uncover any evidence of deterioration which may affect either the containment's structural integrity or leak tightness.

This item is an infraction.