



UNITED STATES
ATOMIC ENERGY COMMISSION

~~COMMUNICATIONS SECTION~~

REGION II - SUITE 818

230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: (404) 526-4503

DIRECTORATE OF REGULATORY OPERATIONS

August 3, 1972

J. B. Henderson, Chief, Reactor Construction Branch
Directorate of Regulatory Operations, Headquarters

FLORIDA POWER CORPORATION (CRYSTAL RIVER 3), LICENSE NO. CPPR-51, DOCKET
NO. 50-302

The attached report of an inspection of the subject facility on May 9-12, May 24-26, and June 12, 1972, is forwarded for information. Two items of noncompliance were discussed in regional office correspondence with the licensee. One of these was similar to an item previously cited and the licensee was asked to describe in his answer to our letter, specific programmatic changes to improve this deficient area. Recently, announced additions to the quality program staff, organizational changes and added emphasis to quality training onsite are expected to cause observable improvements in the site quality program.

Over a period, we have had several misunderstandings with FPC concerning our free access to working level people. As a result of these, the Region II Director, Test and Startup Branch Chief and the principal inspector met with FPC management on June 12, 1972. We believe that no further problems will be encountered in this area.

The following information is supplied in response to potential generic issues and specific Headquarters memoranda:

1. FPC checks indicated that no Westinghouse DB-50 circuit breakers are to be used at Crystal River 3 (RT&OB:AR:48).
2. Valve stems made of 400 series stainless steel are not being used (Inquiry Report No. 50-269/72-1).
3. No PECO paddle-type flow switches are to be used (Henderson memorandum dated June 19, 1972).
4. No G-E CR-120 relays will be used (Inquiry Report No. 50-186/72-3).
5. No reduced flow Velan valves will be used (Henderson memorandum dated March 3, 1972).

8002 280 810

J. B. Henderson

- 2 -

August 3, 1972

6. Only regularly scheduled airline overflights at high altitude have been observed by site personnel (O'Reilly memorandum dated February 1, 1971).
7. Responsible FPC officials agreed to notify Region II of any civil disturbance incident at the site (O'Reilly memorandum dated December 15, 1970).

FF Warnick For

N. C. Moseley, Chief
Reactor Test and Startup Branch

RO:II:NCM

Enclosure:

RO Rpt. No. 50-302/72-2
(Warnick)

cc w/encl:

RS, AD For Safety and Security Stds. (3)
L Asst. Director For Boil. Water Reactors (2)
L Asst. Director For Press. Water Reactors (2)
L Asst. Director For Operating Reactors (3)
L Asst. Director For Site Safety (2)
RO Office of Operations Evaluation
RO Asst. Dir. for Procedures
RO Asst. Dir. for Inspection & Enforcement
RO Files
DR Central Files