

NUCLEAR REGULATORY COMMISSION

REGION II

230 PEACHTREE STREET, N. W. SUITE 818
ATLANTA, GEORGIA 30303
MAR 2 1976

In Reply Refer To: IE:II:KWW 50-302/76-4

## Gentlemen:

This refers to the inspection conducted by Mr. W. L. Britz of this office on February 9-13, 1976, of activities authorized by NRC Construction Permit No. CPPR-51 for the Crystal River 3 facility, and to the discussion of our findings held with Mr. G. P. Beatty at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office requesting that such information be withheld from public disclosure. If no proprietary information is identified, a written statement to that effect should be submitted. If an application is submitted, it must fully identify the bases for which information is claimed to be proprietary. The application should be prepared so that information sought to be withheld is incorporated in a separate paper and referenced in the application since the application will be placed

in the Public Document Room. Your application, or written statement, should be submitted to us within 20 days. If we are not contacted as specified, the enclosed report and this letter may then be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Very truly yours,

F. J. Long, Chief

Reactor Operations and Nuclear Support Branch

Enclosure: IE Inspection Report No. 50-302/76-4