

Appendix A  
Notice of Violation

Based on the results of the NRC inspection on June 6-10, 1977, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your NRC Facility License No. DPR-72 as indicated below. This is a deficiency.

- A. Technical Specifications section 6.12.2.d requires that the licensee maintain a respiratory protection program which is consistent with ANSI F88.2-1969 and which includes written procedures to assure proper training of personnel using protective equipment and written procedures to assure full effectiveness of the respiratory protective equipment, including cleaning, decontamination and storage.

Contrary to the above the licensee's protection program has not been implemented in accordance with the requirements of written procedures.

1. The licensee's approved retraining program specifies a retraining frequency of two years while the respiratory protection program specified an annual retraining frequency for respiratory protection training. Also, the retraining program does not include the periodic training in respiratory protection for licensed operators although the respiratory protection program requires annual retraining of all individuals in the program.
2. Respirators were not packaged or stored in accordance with the requirements of the respiratory protection program procedures in that respirators were not individually bagged to maintain cleanliness or stored in a manner to prevent damage or taking a set.

8002 280 915