

FS&EB ACTION CONTROL FORM

A. Action Code III/73-23  
 Name of Licensee and Facility Davis Besse  
 Docket No. or License No. 50-346  
 Title CRO Breaker Undervoltage Trip Assembly Deficiencies  
 Origin Henderson memo to Knuth Date Rec'd 5/11/73

B. FS&EB Branch Coordinator:  
 Bryan X Dreher \_\_\_\_\_  
 Ellis \_\_\_\_\_ Paulus \_\_\_\_\_  
 Completion Requested by \_\_\_\_\_

C. Action Requested of:  
 ADREMP \_\_\_\_\_ M&PPOB \_\_\_\_\_ EPB \_\_\_\_\_ RPB \_\_\_\_\_ ADCO \_\_\_\_\_  
 OB \_\_\_\_\_ CB \_\_\_\_\_ TAB \_\_\_\_\_ OOE \_\_\_\_\_ Region III  
 Date Requested 5/16/73 Completion Requested by 5/25/73  
 Reference Memo Thomas to Keppler (5/1/73)

D. Action Requested  
 Request followup to determine that corrective action is taken at Davis Besse with regard to the Breaker undervoltage Trip Assembly Deficiency as experienced at Oconee Unit No. 1

E. Date Action Completed Sept. 13 1973 *RO Inspection Report No 050-346/73-0*  
 Close-out (Date & Method) RO Inspection Report No 050-346/73-0  
 Comments: If completion date is not consistent with your work schedule, please let us know.

*Harold D. Thornburg*  
 Harold D. Thornburg, Chief  
 Field Support & Enforcement Branch  
 Regulatory Operations