



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

May 25, 1972

J. B. Henderson, Chief, Reactor Construction Branch
Directorate of Regulatory Operations, Headquarters

VENDOR INSPECTION REPORT
GRINNELL COMPANY, KERNERSVILLE, NORTH CAROLINA
BALANCE OF PLANT NUCLEAR PIPING FOR DAVIS-BESSE
DOCKET NO. 50-346

The attached report of a vendor inspection at the subject vendor's plant on May 10 - 12, 1972, is transmitted for information. No items of noncompliance were encountered during the inspection but one item of code nonconformance was discussed at the conclusion of the inspection and has been called to the attention of the licensee by Enclosure to the letter summarizing the results of the inspection.

A handwritten signature in cursive script, reading "W. E. Vetter", is positioned above the typed name.

W. E. Vetter, Chief
Reactor Construction Branch

Attachment:
RO Rpt No. 999-019/72-01 by
R. E. Oller

cc: H. D. Thornburg, RO
G. W. Reinmuth, RO
R. B. Minogue, RS (3)
R. S. Boyd, L (2)
R. C. DeYoung, L (2)
D. J. Skovholt, L (3)
H. R. Denton, L (2)
R. H. Engelken, RO
RO Files
DR Central Files

8001810 513