

LICENSEE EVENT REPORT

CONTROL BLOCK []

LICENSEE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

[01] [0] [H] [D] [B] [S] [1] [1] [0] [0] [0] [0] [N] [P] [F] [1] [0] [3] [4] [1] [1] [1] [1] [1] [0] [1] [1]

REPORT OF EVENT

DOCKET NUMBER

EVENT TIME

REPORT DATE

[01] CONT [1] [T] [L] [0] [5] [0] [0] [3] [4] [6] [0] [8] [2] [2] [7] [7] [0] [8] [0] [2] [7] [7]

EVENT DESCRIPTION

[02] During the "Miscellaneous Instrument Shift Check", it was discovered that [03] two Relative Position Indication Channels in Control Rod Group 6 indicated 0% withdrawn. Absolute Position Indication indicated 21% withdrawn. [05] This placed the unit in violation of Technical Specification 3.1.33. [06] (NP-32-77-15)

SYSTEM CAUSE

POINT COMPONENT

DISPOSITION

VIOLATION

[07] [E] [E] [I] [N] [I] [S] [I] [R] [U] [N] [D] [I] [S] [O] [Y]

CAUSE DESCRIPTION

[08] Component failure was the cause of the occurrence. The API/RPI select [09] relays were operating improperly. [10]

FACILITY STATUS

POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

[11] [B] [0] [0] [0] [NA] [E] [NA]

FORM OF RELEASE

DATE OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

[12] [Z] [Z] [NA] [NA]

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

[13] [0] [0] [Z] [NA]

PERSONNEL INJURIES

NUMBER

DESCRIPTION

[14] [0] [0] [NA]

OFF-SITE CONSEQUENCES

[15] NA

LOSS OR DAMAGE TO FACILITY

TYPE

DESCRIPTION

[16] [Z] [NA]

PUBLICITY

[17] NA

ADDITIONAL FACTORS

[18] NA

[19]

NAME Jacque Lingenfelter/Dean Hitchens

PHONE (419) 259-5000, Ext. 251