

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
01	A	R	A	R	K	I				0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	3	
7	8	9							14	15									25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE												
57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	
CON'T		L	L	0	5	0	-	0	3	1	3	0	3	1	0	7	7	0	4	0	8	7	7	

EVENT DESCRIPTION	DATE	TIME	LOCATION	STATUS
...	...	...	...	...

02 DURING A REFUELING SHUTDOWN, WHILE PERFORMING AN ESAS INTEGRATED
7 8 9 80

03 TEST ON THE PENETRATION ROOM VENTILATION SYSTEM, VALVE CV-2123
7 8 9 80

04 WAS FOUND TO BE INOPERATIVE. THERE WAS REDUNDANT SYSTEM
7 8 9 80

05 AVAILABLE AND OPERABLE. THIS EVENT WAS A REPETITIVE OCCURRENCE. THE
7 8 9 80

06 CIRCUIT BREAKER OVERLOAD HEATERS WERE REPLACED WITH HEATERS OF A HIGHER
7 8 9 80

PRIME (OVER)

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
0	7	A	A	V	A	L	V	E	X	L	Z	a	a	a	N
7	8	9	10	11					12	13	14	15	16	17	
									43					48	

CAUSE DESCRIPTION

08 | THE CIRCUIT BREAKER OVERLOAD HEATERS WERE REPLACED WITH HEATERS
7 8 9
09 | OF A HIGHER AMPERAGE RATING. A ESAS TEST WAS PERFORMED
8 9
AND THE VALVE WAS PROVEN TO BE OPERABLE.

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	H	000	NA	b	NA

FORM OF ACTIVITY RELEASED: 12
CONTENT OF RELEASE: 2
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	7	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	NA

OFFSITE CONSEQUENCES

15 NA 7 8 9 BC

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	2		NA

PUBLICITY

17 NA 800 2.2 80

ADDITIONAL FACTORS

7 8 9 NA

19 | 7 8 9

NAME

DAVID G. MARDIS

PHONE: 501/3

96

GPO 851-007