

ARKANSAS POWER & LIGHT COMPANY

April 8, 1977

IE FILE COPY

1-047-5

Mr. E. Morris Howard, Director
Office of Inspection & Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1

Docket No. 50-313 Licence No. DPR-51

Follow in Report to Reportable Occurrence Report No. 50-313/77-5

(File: 0520)

Gentlemen:

In accordance with Technical Specification 6.12.3.2, we have attached the subject follow-up report concerning a leak on the upstream pipe-to-flange weld of a valve used to vent the Reactor Coolant Pump seals during initial fill of the RCS.

Should additional information be required, please advise.

Very truly yours,

Donald A. Rueter Manager, Licensing

DAR: REI: tw

Attachments

cc: Mr. W. D. MacDonald, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8004140 740 5

MODAMON SHA S

