

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

CON'T

REPORT SOURCE: L 0 5 0 0 0 3 1 3 7 0 6 1 1 8 0 8 0 7 1 0 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During hydrogen purge system surveillance testing per operating

0 3 procedure 1104.33 Sup. II proper flow through the system was unable

0 4 to be obtained. Loop "A" was operable per last surveillance test.

0 5 There were no similar occurrences. Reportable per T. S. 6.12.3.2(b).

0 6

0 7

0 8

0 9

SYSTEM CODE: S E 11

CAUSE CODE: E 12

CAUSE SUBCODE: D 13

COMPONENT CODE: V A L V E X 14

COMP. SURCODE: C 15

VALVE SURCODE: X 16

LER/HO REPORT NUMBER: 18 0 21 22

EVENT YEAR: 8 0 23

SEQUENTIAL REPORT NO: 0 1 6

8 007150

603