


ILLINOIS POWER COMPANY



U-0153

L14-80(07-08)-0

500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

July 8, 1980

Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Stello:

Clinton Power Station Units 1 & 2
Docket Nos. 50-461 and 50-462
Construction Permits No. CPPR-137 & CPPR-138

Mr. H. M. Wescott, Inspector NRC Region III, requested that we review our records on 10CFR50.55(e), Deficiency Reporting, issues relative to the distribution of information copies to your office.

Enclosed are copies of the below listed Illinois Power Company letters sent to NRC Region III regarding 10CFR50.55(e) matters which were inadvertently not sent to NRC Headquarters.

1. Letter 2/26/80 (U-0124), subject matter: defective plug welding on swinging dividers for control room termination cabinets (interim report).
2. Letter 3/31/80 (U-0136), subject matter: use of incorrect soil characteristic value by architect/engineer as design input for developing building response spectra (interim report).
3. Letter 4/30/80 (U-0137), subject matter: breakdown in General Electric Co. C&ID quality system; improper QA documentation provided for some local panels (final report).
4. Letter 6/13/80 (U-0148), subject matter: concrete embeds which provide lateral support for residual heat removal (RHR) heat exchangers not to design specification (interim report).
5. Letter 6/24/80 (U-0150), subject matter: deficiency in control rod drive (CRD) penetration through drywell wall (interim report).

B019

S

1/1


8007160626

U-0153
L14-80(07-08)-0
July 8, 1980

Mr. Victor Stello, Jr. -2-

We apologize for any inconvenience this oversight on our part may have caused. Rest assured that in the future, copies of all correspondence sent to the NRC Region III on deficiency reporting will be forwarded to your office, per 10CFR50.55(e)(3).

Sincerely,



G. E. Wuller
Supervisor - Licensing
Generation Engineering Dept.

GEW/em

Enclosure

cc: J. G. Keppler, NRC Region III (w/o attachment)
H. M. Wescott, NRC Region III
H. H. Livermore, NRC Resident Inspector

ILLINOIS POWER COMPANY

U-0124

L14-80(02-26)-9

500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

February 26, 1980

Mr. James G. Keppler
Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:


Clinton Power Station Units 1 & 2
Docket Nos. 50-461 and 50-462
Construction Permit Nos. CPPR-137 and CPPR-138

The potential reportable condition of which you were verbally notified on 1/28/80 has been reviewed and determined to be covered by the intent of 10CFR50.55(e). The tentative classification has been determined to be in accordance with Paragraph (i), "A breakdown in any portion of the quality assurance program conducted in accordance with the requirements of Appendix B."

Our investigations to date indicate that some CPS control room termination cabinets appear to have defective plug welding on the swinging dividers. We do not however, have sufficient information at this time to determine the full extent of the problem, the appropriate corrective action, or a program for prevention of recurrence.

Because of the insufficient information described above, you are advised that this is to be considered an interim report in accordance with the provisions of Subparagraph (3) of 10CFR50.55(e). We expect to file a complete report in approximately ninety days.

Sincerely,


L. J. Koch
Vice President.

GEW/jh

Due
800325-0482 1P