

CP&L

Carolina Power & Light Company

**Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461**

June 24, 1980

FILE: EOP-13516

SERIAL: BSEP/80-1069

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Room 11, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

**BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2
LICENSE NO. DPR-62
DOCKET NO. 50-324**

CONTINUATION FACSIMILE FOR AN IMMEDIATELY REPORTABLE EVENT (2-80-47)

Dear Mr. O'Reilly:

This facsimile confirms the conversation between Mr. A. C. Tollison, Jr., and Mr. Austin Hadden, of your office, at 0910 on June 24, 1980.

While replacing the nonqualified splices connecting the safety-relief valves solenoids' pigtaills to the nuclear grade cable, addressed in LER 2-80-46, it was discovered that the pigtaills on the solenoids were brittle and that the insulation would crack when handled. Target-Rock was contacted about this problem and they stated that the solenoids in use at Brunswick Steam Electric Plant (BSEP) were not qualified. They provided information to BSEP which allowed us to locate and procure qualified solenoids for the safety-relief valves. These qualified solenoids, along with the qualified splices, will be installed on each unit before startup.

This event is reported under Technical Specification 6.9.1.8i.

Very truly yours,

A. C. Tollison, Jr., General Manager
Brunswick Steam Electric Plant

POOR ORIGINAL

BWP/epb

cc: Mr. E. A. Hatfield
Mr. V. Stello, Jr.

Director
Deputy Director
Ass't to Director
Admin. Officer
RONS Chief
RCES Chief
FFMS Chief
Sfgds Chief
FA Officer
Emergency Officer

A002
S
111

8007160 632

A. Gibson