



ATTACHMENT TO LER  
NO. 80-022/01 T-0  
COMMONWEALTH EDISON CO.  
ZION GENERATING STATION  
50-304

Description of Event

During the ILRT on U-2, it was determined that both PORV's were closed and inoperable.

Consequences of Occurrence

Above condition was in conflict with Tech Spec 3.3.2.G.1.. However, all ESF pumps were OOS or pull to lock, RCP's OOS and accumulator tanks vented to containment, therefore eliminating any probability of overpressurization.

Cause of Occurrence

The PORV's became inoperable when the accumulators for PORV's were vented and instrument air isolated. This condition was required for ILRT.

Corrective Actions

In the future, PORV's will be blocked open during the ILRT.